

Report ID: 15,447,259 Version: 3 18 Jan 2019 Created:

Signature:

		Pass F	ail N/A
	Engine		
WoF Expiry: 12 Sep 2018 Odometer: 365,612 Kms Good No: 15447259	Oil level	~	
VIN: JT732LNF200001132 Next Service: 368,708 Service History: Yes	Smoke & fumes	~	
	Performance	~	
Note: This report is not a warranty	Noise	~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends	Cooling System	•	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	Coolant condition	~	
	Performance	~	
Key: SDRW W SPW SDR W	Radiator / Hoses (visual)	~	
S = scratch	Transmission	V	
D=dent SDCSC	Operation		
	Noise	マ マ	
PT = paint defect C = crack	Clutch	•	
P = pin dent		~	
*=decals SSC QQ	CV joints		~
SC = stone chips	Wheel bearings	~	
W = significant scuffs S D SC W S D R PW S PW R W	Brakes		
	Performance	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	 	
L'H park light clacked & loose. Drivers door check strap missing.	Tyres (lowest observed tread	l depth of	tyres)
L/H tail light cracked. Fine chips on screen. Aerial broken, temporary one installed. No tools, just jack.	Left front	6	mm
	Right front	5	mm
After market r/h wing mirror. R/H guarter window broken, wooden one fitted.	Left rear	4	mm
Conditions During Body Inspection: Dry	Right rear	5	mm
	Spare	Y	(es
	Suspension		
Oil leaks under engine & gearbox.	Suspension performance	~	
	Steering performance	~	
	Shock absorbers	~	
	Air Conditioning / Heater		
	Operation		~
	Electrical / Accessories		
Seats holes in drivers seat, dirty.	Head lights	~	
holes on drivers side, dirty.	Tail lights	~	
Carpets	Indicators	~	
Panels console lid missing.	Dashboard warning lights	~	
screw holes.	Wipers (front & rear)	~	
Dashboard	Window winder FL	~	
	Window winder FR	~	
<u>General Comments</u>	Window winder RL		~
OK, but very untidy flat deck pickup truck.	Window winder RR		~
	Rear view mirrors		~
	Radio (basic test only)	~	
	CD (basic test only)		~
	Number of keys	1	I
Pead Canditiana Duving Test Duiver	Central locking		~
I ROAD CONDITIONS DURING LEST DUVE: DV	Remote locking		~
Road Conditions During Test Drive: Dry	-		
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)		~
	Sat. Nav. (basic test only) Reversing camera		✓✓

I have read and understood this condition guide.

Name: