

Report ID: 16,347,365


Version:

Created: 09 Mar 2017

| Make: | Hyundai | Model: | H1 | Body Style: | Van |
|-------------|-------------------|---------------|-------------|----------------|-------------|
| Year: | 2,011 | Registration: | FTD816 | Reg Expiry: | 16 Apr 2017 |
| WoF Expiry: | 10 Feb 2018 | Odometer: | 157,274 Kms | Good No: | 16347365 |
| VIN: | KMFWBX7JLBU305144 | Next Service: | 166375 | Service Histor | y: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Number of stone chips in windscreen, hi stop light cracked, large dent in right sill,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leaks engine and intercooler areas,

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Poor | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Poor | | | |

General Comments

Rattle in motor on start up, dash has a number of screw holes in it, drivers seat torn, only one remote key,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 09 Mar 2017 Inspected by: Steve Ingram

Name:

| | Pass | Fail | N/A |
|--|-----------------------|---------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | \(\triangle \) | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | V V | | |
| Transmission | ı | | ! |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | ~ | | |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | ⊥ ≥s) |
| Left front | | .1 | mm |
| Right front | 4.6 | | mm |
| Left rear | 8.6 | | mm |
| Right rear | 8.2 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | l |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | V | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | | | |
| | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Wipers (front & rear) Window winder FL | | | |
| Wipers (front & rear) Window winder FL Window winder FR | \(\times \) | | |
| Window winder FL | v | | |
| Window winder FL Window winder FR Window winder RL | v | | <i>V</i> |
| Window winder FL Window winder FR Window winder RL Window winder RR | \(\times \) | | <i>v</i> |
| Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors | v | | <i>V</i> |
| Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) | V V V V V | | <i>V</i> |
| Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) | V V V V | | <i>V</i> |
| Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys | V V V V 2 | | <i>V</i> |
| Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking | V V V V | | v v |
| Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking | V V V V 2 | | V V |
| Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking | V V V V 2 | | V V V |

Signature: