

## **Basic Vehicle Condition Guide**

Report ID: 16,359,949

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 07 Jul 2017

Pass

1

/

/

V

1

N/A

1

mm

mm

mm

mm

4.0

3.0

4.0

1

/

/

1

1

1


Yes

Fail

Make: Model: **Body Style:** Sedan Subaru Legacy Year: 2,005 Registration: **Reg Expiry:** HHK722 22 Aug 2017 WoF Expiry: **Odometer: Good No:** 16359949 27 Jun 2018 126,587 Kms VIN: **Next Service: Service History:** 7AT0GF0BX12040960 129000 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Average		
Dashboard	Good		

## **General Comments**

4 wheel drive

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

Stanley Chen

I have read and understood this condition guide.

**Evidence of Cam Belt Replacement:** No

	Remote locking	~		
	Sat. Nav. (basic test only)		~	
Kms:	Reversing camera		V	
Date: 30 Mar 2017				
Name:	Signature:			