

Report ID: 16,385,529 Version: 1 Created: 03 May 2017

Make:	Ford	Model:	Fiesta	Body Style:	Hatchback][Pass	Fail	N/A	
Year:	2,014	Registration:	HHS410	Reg Expiry:	20 Jun 2017		Engine				
WoF Expiry:	22 Mar 2018	Odometer:	61,045 Kms	Good No:	16385529	ļŀ	Oil level	~			
VIN:	MNB8XXARJ8EY24656	Next Service:	75735	Service Histor	y: No	lŀ	Smoke & fumes	~			
						il	Performance	~			
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	lİ	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechar	ical inspection prior to	purchase and t	nis can be arranged fo	r an additional c	harge.	lŀ	Coolant condition	~			
						۱İ	Performance	~			
Key:		-0		$- \alpha^{\mathbb{W}}$		lŀ	Radiator / Hoses (visual)	~			
S = scratch							Transmission			1	
D = dent R = rust	s sc			TIS	HILLS	ŀ	Operation	~			
PT = paint def				$\left[\right] \left[\right]$		lŀ	Noise	~			
C = crack							Clutch			~	
P = pin dent	HIG				ᅰ	lŀ	CV joints	~			
* = decals	DSC 91			-No-	ALD S	lŀ	Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs SC W S P W						lŀ	Performance	~			
D = -1 - 1		Note: son	ne defects & blemishes	may not be disp	layed in the diagram		Hand Brake	~			
Body Inspection Comments						ļŀ	Tyres (lowest observed tread	-	of tyre	es)	
						lŀ	Left front 7 mm				
						lŀ	Right front			mm	
						Jŀ	Left rear			mm	
Conditio	os During Body Ins	oection:	Wet			1 ŀ	Right rear			mm	
Conditions During Body Inspection: Wet						ļŀ	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
						lŀ	Suspension performance	~			
						lŀ	Steering performance	~			
						lŀ	Shock absorbers	~			
							Air Conditioning / Heater	•			
							Operation	~			
Interior Comments							Electrical / Accessories				
Seats	Good					lŀ	Head lights	~			
	Card					lŀ	Tail lights	~			
Carpets	Good						Indicators	· ·			
Panels	Good						Dashboard warning lights	~			
						╎┝	Wipers (front & rear)	~			
Dashboa	ord Good					lŀ	Window winder FL	~			
	I					┙ ╎	Window winder FR	~			
General Comments						lŀ	Window winder RL	~			
Right rear seatbelt damaged						lŀ	Window winder RR	~			
						lŀ	Rear view mirrors	~			
						lŀ	Radio (basic test only)	~			
							CD (basic test only)	~			
						Jŀ	Number of keys	2		1	
Road Conditions During Test Drive: Dry						٦ŀ	Central locking	~			
Road Conditions During Test Drive: Dry						┛┠	Remote locking	~			
Engine Timing Mechanism: Cambelt							Sat. Nav. (basic test only)	-		~	
Evidence of Cam Belt Replacement: No Kms:							Reversing camera			~	
						11	J			-	
Inspected by: Dave Fishwick Date: 03 May 2017											

I have read and understood this condition guide.

Name:

Signature: