

Report ID: 16,385,909 Version: 5 Created: 18 Jul 2017

Make:	Isuzu	Model:	Bighorn	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,998	Registration:	EDL532	Reg Expiry:	19 Sep 2017	Engine	1	L	
WoF Expiry:	15 Oct 2017	Odometer:	201,245 Kms	Good No:	16385909	Oil level		~	
VIN:	7A897130707204107	Next Service:	204000	Service Histor	V: No	Smoke & fumes		~	
						Performance		~	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance		~	
Key: S S S S						Radiator / Hoses (visual)		~	
S = scratch D = dent R = rust PT = paint defect C = crack						Transmission			
						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
* = decals S 000 SD						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S P S D						Performance 🖌			
Noto: come defecte % blomiches may not be displayed in the displayer						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			 >s)
Stone chips in windscreen									
						Right front		0.0	
						Left rear	0.0		mm
Conditions Duving Rody Inspection.						Right rear	0.0		mm
Conditions During Body Inspection: Dry						Spare	0.0		
Under Carriage & Under Bonnet Inspection Comments						Suspension Yes			
Oil leaks 4x4						Suspension performance	~		1
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						┛┝─────			
Interior Comments						Electrical / Accessories	~		
Good						Head lights			1
Seats						Tail lights	ン ン		
Carpets	Good								
	Good				Indicators	~			
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
General Comments CRACKED HEAD GASKET						Window winder RL	~		
Radio static noise. Engine miss firing at idle.Low battery voltage. Slow cranking. Takes long to fire cold.Both front outter CV boots leaking grease.Recomend wheel alignment.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Ti	ning Mechanism	Cambal	+			Remote locking			~
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 164,000						Sat. Nav. (basic test only)			~
	or carri bert nepiac	cincili. Y	′es	1113. [6	94,000	Reversing camera			~
Inspected by: Eddie Marsters Date: 18 Jul 2017									
I have read and understood this condition guide. Name:									