

Report ID: 16,429,005 Version: 2 Created: 01 May 2017

Make:	Mitsubishi	Model:	Mirage	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,013	Registration:	HAK106	Reg Expiry:	15 Aug 2017	Engine	1		1
WoF Expiry:	16 Aug 2017	Odometer:	41,194 Kms	Good No:	16429005	Oil level	~		
VIN:	MMAXTA03AEH01039	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	sc sc		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent R = rust	sc			715	HILLS	Operation	~		
PT = paint def	ect NP	F		$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch			V
P = pin dent	HID				거네니	CV joints	~		
*= decals SC 919 S						Wheel bearings	~		
SC = stone chips						Brakes	-		
W = significant scuffs S S S S S S P						Performance	~		
Note: come defecte % blamiches may not be displayed in the diagram						Hand Brake	~		+
Body Inspection Comments						Tyres (lowest observed tread		of tyre	es)
Stonechips on windscreen.						Left front 4 m			
						Right front		+ 1	mm
						Left rear		<u>•</u>	mm
Conditio	as During Pody Ins	oction	D			Right rear			mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Good cond	-	<b>-</b>				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		1
Interior Comments						Electrical / Accessories	V		
Seats	Good					Head lights	~		1
Seals						Tail lights			
Carpets	Good						~		
D 1	Good					Dashboard warning lights	~ ~		
Panels						Wipers (front & rear)			
Dashboa	rd Good					Wipers (front & rear) Window winder FL	V		
							~		
General (	Comments					Window winder FR	~		
Drives ok.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
LVIGENCE			lot Applicable	11115.		Reversing camera			~
Inspected by: Roger King						Date: 01 May 2017			
	,					U			
I have read	and understood th	is condition o	juide. Name: .			Signature:			