

Report ID: 16,431,933 Version: 3 Created: 29 Jun 2017

Make:	Ford	Model:	Mondeo	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,013	Registration:	GYC329	Reg Expiry:	18 Jun 2017	Engine	1	I	
WoF Expiry:	14 Jun 2017	Odometer:	89,216 Kms	Good No:	16431933	Oil level	~		
VIN:	WF0GXXGBBGCS8396	Next Service:	108,000kms	Service Histor	y: Yes	Smoke & fumes	~		
			•			Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	SC S D	-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent B = runt SDSC						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch			~
P = pin dent						CV joints	~		-
*=decals SPSC 919						Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs						Performance V			
		Note: son		may not be disc		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftyre	
L/H wing mirror indicator lens cracked. Stone chipped screen.						Tyres (lowest observed tread depth of tyres) Left front 4			
Stone empleu sereen.							4 mm		
						Right front Left rear		1	mm
								1	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
						Suspension			
Tidy & dry.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories	1		1
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	9000					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
						Window winder FR	~		ļ
General Genera	<u>Comments</u>					Window winder RL	~		
Nice anving	y wagon.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Dave Fishwick Date: 29 Jun 2017									
I have read and understood this condition guide. Name:									