

Basic Vehicle Condition Guide

Report ID: 16,434,336


Version: 3

Created: 06 Jul 2017

Make: Model: lsis **Body Style:** SUV Toyota Year: 2,005 Registration: KGT146 Reg Expiry: 21 Jun 2017 **WoF Expiry: Odometer:** 23 Dec 2017 **Good No:** 103,689 Kms 16434336 VIN: 7AT0H658X16798484 **Next Service: Service History:** 110198 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

All wheel drive CD not working

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Rahul Singh Date: 31 May 2017

	Pass	Fail	N/A
Engine	Pass	raii	IN/F
Oil level	·		
Smoke & fumes	~		
Performance	V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	V		
Noise	~		
Clutch	ļ -		_
CV joints	~		
Wheel bearings	<i>y</i>		
Brakes			
Performance	·		
Hand Brake	1/		
Tyres (lowest observed tread	l denth	of tyre	-c)
Left front		.0	mm
Right front			mm
Left rear		.0	mm
Right rear	3.0		mm
Spare	3	Yes	
Suspension		163	
Suspension performance	V		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	•		
Operation	~		
Electrical / Accessories			
Head lights	V		
Tail lights	<i>V</i>		
Indicators	V V		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	\(\times \) \(\t		
Window winder RR	~		
Rear view mirrors	v		
Radio (basic test only)	~		
CD (basic test only)		~	
Number of keys	1	_	<u> </u>
Central locking			
Remote locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Sat. Nav. (basic test only)			1
Reversing camera	~		
eversing cumera		<u> </u>	

I have read and understood this condition guide.

Name:

Signature: