

Report ID: 16,436,790 Version: 2 18 Jun 2018 Created:

| Make: | Toyota | Model: | Highlander | Body Style: | SUV | | Pass | Fail | N/A |
|--|------------------------|----------------------|------------------------|-----------------|-------------------------|--|--------|----------------|-----|
| Year: | 2,015 | Registration: | JDZ244 | Reg Expiry: | 14 Dec 2018 | Engine | | | |
| l | 2,015 19 Jun 2019 | Odometer: | 78,661 Kms | Good No: | 14 Dec 2018 16436790 | Oil level | ~ | | |
| VIN: | 5TDBK3FH00S143805 | | 91,000 | Service Histor | | Smoke & fumes | ~ | | |
| | 51220311005115005 | | 51,000 | | 103 | Performance | ~ | | |
| | port is not a warranty | | ~ · · · | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | S | -0 | S SC S SC | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | STE | A CO | | 10c | T | Transmission | v | | L |
| D = dent | scw 6/6 | | | 1n- | | Operation | ~ | | |
| R = rust | | | | 10 | JHIH | Noise | ~ | | |
| PT = paint defe C = crack | | | | $\square \cup$ | | Clutch | ~ | | ~ |
| P = pin dent | Ho | | | | JUII — | CV joints | ~ | | ~ |
| * = decals | SPSC PIC | | | AL- | ETTR | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | | | | |
| | | Noto: com | le defects & blemishes | | layed in the diagram | Hand Brake | ~ | | |
| Body Insp | pection Comments | Note. son | le delects & blemisnes | may not be disp | layed in the diagram | | | - f h m | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 4. | | mm |
| | | | | | | Right front | 4. | | mm |
| | | | | | | Left rear | 6. | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6.5 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | | <u>incernspectic</u> | <u>in comments</u> | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | 1 |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation 🖌 | | | |
| Good | | | | | | Electrical / Accessories | | | |
| Seats | | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | Good | | | | | Indicators | ~ | | L |
| Panels | | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | |
| Dushibou | | | | | | Window winder FL | ~ | | |
| Conoral C | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | |
| | ning Machaniers | | -1 · | | | Remote locking | ~ | | |
| - | ning Mechanism: | Timing (| | K. | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Inspected by: Ian Dunn Date: 03 May 2017 | | | | | | | | | |
| | | | | | | Date. 05 May 20 | | | |

I have read and understood this condition guide.

Name:

Signature: