

Report ID: 16,446,181 Version: 3 12 May 2017 Created:

Make:	Hyundai	Model:	Santa EE	Body Style:	STIN/	-	Pass	Fail	N/A
	Hyundai		Santa FE	Reg Expiry:	SUV	Engine	r ass	rall	
Year: WoF Expiry:	2,009	Registration: Odometer:	GRW586	Reg Expiry: Good No:	08 Nov 2017				
	25 May 2018		68,690 Kms		16446181	Oil level	~		
VIN:	KMHSH81DR9U43055	Next Service:	72,000	Service Histor	Y: Yes	Smoke & fumes	~		
Note: This re	port is not a warranty					Performance	~		
	a guide only. Conside					Noise	~		
	sting undertaken. The vical inspection prior to					Cooling System			
						Coolant condition	~		
Key:	SC W		SC W SC W			Performance	~		
S = scratch	~	(0)		(0)	\checkmark	Radiator / Hoses (visual)	~		
						Transmission			
R = rust	scw 96				HIV	Operation	~		
PT = paint def	ect N					Noise	~		
C = crack						Clutch			~
P = pin dent * = decals	sc dk			SI_	出出	CV joints	~		
SC = stone chi		10		10		Wheel bearings	~		
W = significant scuffs						Brakes			
	W	\sim	S SC W		S W	Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	3.	.0	mm
						Right front	3.	.0	mm
						Left rear	3.	.0	mm
Conditions During Body Inspection: Wet						Right rear	3.	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
							I		
Inspected by: Scott Willoughby Date: 12 May 2017									
I have read and understood this condition guide. Name:									