

Basic Vehicle Condition Guide

Report ID: 16,451,535


Version:

Created: 10 May 2017

Make: Model: Mazda **Body Style:** SUV Premacy Year: 2,006 Registration: Reg Expiry: HZS138 23 Jul 2017 **WoF Expiry: Odometer:** 04 May 2017 **Good No:** 128,490 Kms 16451535 VIN: **Next Service:** Service History: 7AT0C133X15151814 120097

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

No key. Door glass rubbers worn out.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Good.

| <u>Interior Comments</u> | | |
|--------------------------|---------|--|
| Seats | Average | |
| Carpets | Average | |
| Panels | Good | |
| Dashboard | Good | |

General Comments

Runs well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

10 May 2017 Inspected by: Brian Hill Date:

Name:

| Pass | Fail | N/A |
|--|-----------------|-----|
| | | |
| ~ | | |
| ~ | | |
| ~ | | |
| ~ | | |
| | | |
| ~ | | |
| ~ | | |
| ~ | | |
| | | |
| ~ | | |
| ~ | | |
| | | ~ |
| ~ | | |
| ~ | | |
| | | |
| ~ | | |
| ~ | | |
| d depth | of tyre | es) |
| | 3 | mm |
| | | mm |
| _ | | mm |
| | | mm |
| _ | | |
| | 103 | |
| V | | |
| <i>y</i> | | |
| ~ | | |
| _ | | |
| | | |
| V | | |
| ~ | | |
| <i>V</i> | | |
| <i>v</i> | | |
| ~ | | |
| v | | |
| \(\times \) | | |
| \(\times \) | | |
| \(\times \) \(\t | | |
| \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| V V V V V | | |
| V V V V V | | |
| V V V V V V | | |
| V V V V V V V | | |
| V V V V V V V | V | |
| V V V V V V V | | |
| | V V V V V depth | · |

Signature: