

Report ID: 16,460,606 Version: 1 12 Jul 2017 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail N/A	
Year:	2,008	Registration:	KMH164	Reg Expiry:	11 Jan 2018	Engine	-		
WoF Expiry:	11 Jul 2018	Odometer:	62,353 Kms	Good No:	16460606	Oil level	~		
VIN:	6G1EX55W19L208567	Next Service:	,	Service Histor		Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty	oration is made	for any and milages	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	S	-0	P S	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission	Transmission		
D = dent R = rust	s dl			ZIS	SP SP	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch	~		
P = pin dent	110				74 <u>11</u>	CV joints		~	
* = decals	- Alf			TO		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan			S S		S	Performance	~		
Bodylog		Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
	Dection Comments					Tyres (lowest observed tread	d depth	of tyres)	
Spare wheel loose.Moist in both taillight lens.					Left front 8 mm				
						Right front	8		
						Left rear	5		
Conditions During Body Inspection: Wet					Right rear	5 mm			
Conditions During Body Inspection: Wet					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension		105		
RWD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I				J	Window winder FR	~		
General Comments					Window winder RL	~			
Fog light not working. Glove box handle loose.Center consule lid missing.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	
Road Conditions During Test Drive: Dry						Central locking	· •		
			у			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera		~	
Inspected by: Eddie Marsters Date: 12 Jul 2017									

I have read and understood this condition guide.

Name:

Signature: