

Report ID: 16,482,377 Version: 1 Created: 29 May 2017

Make: Ford Model: Mondeo Body Style: Hatchback Pass Year: 2,011 Registration: FSQ724 Reg Expiry: 01 Jun 2017 Oil level V WoF Expiry: 13 Feb 2018 Odometer: 187,339 Kms Good No: 16482377 Oil level ✓ VIN: WF0EXXGBBEAU2675 Next Service: Service History: No Smoke & fumes ✓ Note: This report is not a warranty This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantiled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Point Cooling System Cooling System Coolant condition ✓		
WoF Expiry: 13 Feb 2018 Odometer: 187,339 Kms Good No: 16482377 VIN: WF0EXXGBBEAU2675 Next Service: Service History: No Note: This report is not a warranty This report is not a warranty Performance ✓ This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Oil level ✓		
VIN: WF0EXXGBBEAU2675 Next Service: Service History: No Note: This report is not a warranty Smoke & fumes Image: Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Smoke & fumes Image: Parts have not been dismantled or Cooling System		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		
Performance 🖌		
Key:		
S = scratch		
D = dent R = rust S C Operation V		
PT = paint defect Noise 🗸		
C = crack		~
P = pin dent		
* = decals S PT SC 9 9 Wheel bearings V		
SC = stone chips W = cignificant cruffr Brakes		
W = significant scuffs S S Performance V		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Hand Brake		
Tyres (lowest observed tread depth of	of tyres)	
Left front 2	m	nm
Right front 3	m	nm
Left rear 3	m	nm
Conditions During Body Inspection: Dry Right rear 5	m	nm
	Yes	
Under Carriage & Under Bonnet Inspection Comments Suspension		
Dirty Suspension performance 🗸		
Steering performance 🖌		
Shock absorbers 🗸		
Air Conditioning / Heater		
Operation V		
Interior Comments Electrical / Accessories		
Seats Head lights 🖌		
Carpets Average Tail lights 🗸		
Panels Average Dashboard warning lights ✓		
Dashboard Average Wipers (front & rear)		
Dashboard Window winder FL ✓		
Window winder FR 🗸		
General Comments Window winder RL Road noise from tyres Window winder RL		
Koad holse from tyres Window winder RR Drives OK V		
Rear view mirrors 🖌		
Radio (basic test only) 🖌		
CD (basic test only)		
Number of keys 1		
Road Conditions During Test Drive: Dry		
Remote locking		
Enging Timing Machanism:		~
Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only) Sat. Nav. (basic test only)		
Engine Timing Mechanism:CambeltSat. Nav. (basic test only)Evidence of Cam Belt Replacement:NoKms:Reversing camera		~
Suidence of Com Bolt Deple comparts and Kings		<u>~</u>

I have read and understood this condition guide.

Name:

Signature: