

Basic Vehicle Condition Guide

Report ID: 16,483,272


Version: 2

Created: 01 May 2018

Make: Model: Highlander **Body Style:** SUV Toyota Year: 2,015 Registration: JDP533 Reg Expiry: 09 Jun 2017 **WoF Expiry: Odometer:** 19 Sep 2018 **Good No:** 78,384 Kms 16483272 VIN: 5TDBK3FH40S144522 **Next Service:** 82000 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chip windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

01 May 2018 Inspected by: Rahul Singh Date:

Name:

Pass	Fail	N/A
•		
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
	5	mm
5		mm
7		mm
7 mm		mm
Yes		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
3	1	-
~		
~		
		~
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ

Signature: