

Report ID: 16,487,447 Version: 1 Created: 01 Jun 2017

Make:	Toyota	Model:	Landcruiser Prado	Body Style:	SUV		Pass	Fail	N/A
Year:	2,012	Registration:	GKY226	Reg Expiry:	15 Jul 2017	Engine			
WoF Expiry:	2,012 20 Jul 2017	Odometer:	181,081 Kms	Good No:	15 Jul 2017 16487447	Oil level	~		
VIN:	JTEBH3FJ90K075931	Next Service:	187,750kms	Service Histor		Smoke & fumes	~		
	JTEBI 31 390K07 393 1				. 163	Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System Coolant condition			1
						Performance	~		
Key:	S P W	0	S				~		
S = scratch						Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust				10	SHIY	Operation	~		
PT = paint def	ect			$\square \cup$	SC	Noise	~		
C = crack P = pin dent	LH					Clutch			~
* = decals	DSC DIC				ELA SD	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs SC W SC P SC W S						Brakes			
					S	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Roof moulding pieces missing.						Tyres (lowest observed tread depth of tyres)			es)
Stone chips on screen.						Left front	7 mm		mm
						Right front		7	mm
						Left rear	8	3	mm
Conditions During Body Inspection: Dry						Right rear	8	3	mm
						Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
OK, dry.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		-	
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Nice driving	g 4x4 SUV.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Tes	t Drive	Dry			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		+
						<u> </u>	1		
Inspected by: Daryll Timms Date: 01 Jun 2017									
I have read	and understood th	is condition c	uide. Name:			Signature:			