

Report ID: 16,489,356 Version: 2 Created: 08 Jun 2017

| Make:  | Land Rover                 | Model:           | Discovery        | Body Style:    | Wagon            |   | Pass         | Fail    | N/A |
|--|----------------------------|------------------|------------------|----------------|------------------|---|--------------|---------|-----|
| Year:  | 1,999                      | Registration:    | JFT214           | Reg Expiry:    | 27 Nov 2017      | Engine  | 1            | I       |     |
| WoF Expiry:  | 01 Jun 2017                | Odometer:        | 192,236 Kms      | Good No:       | 16489356         | Oil level                                       | ~            |         |     |
| VIN:   | SALLJRMM3VA74472(          | Next Service:    | 177000           | Service Histor | <b>y:</b> No     | Smoke & fumes                                   | ~            |         |     |
|  |                            |                  |                  |                |                  | Performance                                     | ~            |         |     |
| Note: This report is not a warranty<br>This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or   |                            |                  |                  |                |                  | Noise   | ~            |         |     |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |                            |                  |                  |                |                  | Cooling System                                  |              |         |     |
|  |                            |                  |                  |                |                  | Coolant condition                               | ~            |         |     |
|  |                            |                  |                  |                |                  | Performance                                     | ~            |         |     |
| Key:   | sc                         | -0               | SR SR            | -01-           | S D PT           | Radiator / Hoses (visual)                       | ~            |         |     |
| S = scratch  |                            |                  |                  |                |                  | Transmission                                    |              |         | 1   |
| D = dent<br>R = rust   |                            |                  |                  |                |                  | Operation                                       | ~            |         |     |
| PT = paint defect  |                            |                  |                  |                |                  | Noise   | ~            |         |     |
| C = crack  |                            |                  |                  |                |                  | Clutch  |              |         | ~   |
| P = pin dent   |                            |                  |                  |                |                  | CV joints                                       | ~            |         |     |
| *= decals SC 99 SD   |                            |                  |                  |                |                  | Wheel bearings                                  | ~            |         |     |
| SC = stone chips   |                            |                  |                  |                |                  | Brakes  |              |         |     |
| W = significant scuffs   |                            |                  |                  |                |                  | Performance 🖌                                   |              |         |     |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram  |                            |                  |                  |                |                  | Hand Brake                                      | ~            |         |     |
| LHR indicator light in bumper is broken,   |                            |                  |                  |                |                  | <b>Tyres</b> (lowest observed tread depth of ty |              | of tyre | 2S) |
|  |                            |                  |                  |                |                  | Left front                                      | Left front 6 |         | mm  |
|  |                            |                  |                  |                |                  | Right front                                     |              | 6 m     |     |
|  |                            |                  |                  |                |                  | Left rear                                       |              | 5       | mm  |
| Conditio   | ns During Body Ins         | pection:         | Dry              |                |                  | Right rear                                      |              | 5       | mm  |
|  |                            |                  |                  |                |                  | Spare Yes                                       |              |         |     |
| Under Carriage & Under Bonnet Inspection Comments  |                            |                  |                  |                |                  | Suspension                                      |              |         |     |
|  |                            |                  |                  |                |                  | Suspension performance                          | ~            |         |     |
|  |                            |                  |                  |                |                  | Steering performance                            | ~            |         |     |
|  |                            |                  |                  |                |                  | Shock absorbers                                 | ~            |         |     |
|  |                            |                  |                  |                |                  | Air Conditioning / Heater                       |              | 1       |     |
| L  |                            |                  |                  |                |                  | Operation                                       |              | ~       |     |
| Interior Comments  |                            |                  |                  |                |                  | Electrical / Accessories                        | 1            |         | ·   |
| Seats  | drivers sea                | t worn and torn, | broken base pad. |                |                  | Head lights                                     | ~            |         |     |
| <u> </u>   | Average                    |                  |                  |                |                  | Tail lights                                     | ~            |         |     |
| Carpets  | , weitige                  |                  |                  |                |                  | Indicators                                      | ~            |         |     |
| Panels   | Good                       |                  |                  |                |                  | Dashboard warning lights                        |              | ~       |     |
|  | , stereo doe               | sn't work        |                  |                |                  | Wipers (front & rear)                           | ~            |         |     |
| Dashboa  | ird                        |                  |                  |                |                  | Window winder FL                                | ~            |         |     |
|  | · ·                        |                  |                  |                |                  | Window winder FR                                | ~            |         |     |
| General Comments   |                            |                  |                  |                | Window winder RL |   | ~            |         |     |
| Squeaky be   | elts,ABS light is on,low o | n water- radiato | r.               |                |                  | Window winder RR                                |              | ~       |     |
|  |                            |                  |                  |                |                  | Rear view mirrors                               | ~            |         |     |
|  |                            |                  |                  |                |                  | Radio (basic test only)                         |              | ~       |     |
|  |                            |                  |                  |                |                  | CD (basic test only)                            |              | ~       |     |
|  |                            |                  |                  |                |                  | Number of keys                                  | 3            |         |     |
| Road Conditions During Test Drive: Dry   |                            |                  |                  |                |                  | Central locking                                 | ~            |         |     |
|  |                            |                  |                  |                |                  | Remote locking                                  | ~            |         |     |
| Engine Timing Mechanism: Unknown   |                            |                  |                  |                |                  | Sat. Nav. (basic test only)                     |              |         | ~   |
| Evidence   | of Cam Belt Replac         | ement: N         | lot Applicable   | Kms:           |                  | Reversing camera                                |              |         | ~   |
|  |                            | ·                |                  |                |                  |   |              |         |     |
| Inspected by: Donovan Matara Date: 08 Jun 2017   |                            |                  |                  |                |                  |   |              |         |     |
| I have read and understood this condition guide. Name:   |                            |                  |                  |                |                  |   |              |         |     |