

Basic Vehicle Condition Guide

Report ID: 16,510,714


Version:

Created: 15 Jun 2017

Make: Model: Mazda **Body Style:** Utility **Bounty** Year: 2,003 Registration: BSL914 Reg Expiry: 22 Apr 2018 **WoF Expiry: Odometer:** 10 Nov 2017 **Good No:** 16510714 216,551 Kms VIN: MM0UNY0W2003099 **Next Service: Service History:** 220000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Right tail light cracked and not working.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Good.

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

C = = = = =	C
Generai	Comments

Inspected by:

Runs well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Brian Hill

Evidence of Cam Belt Replacement: Kms: Yes 103,326

> 15 Jun 2017 Date:

	Pass	Fail	N/A
Engine		1	
Oil level	~		
Smoke & fumes	VVV		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	VVV		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	2		mm
Right front	3		mm
Left rear	10		mm
Right rear	10		mm
Spare		Yes	
Suspension			
Suspension performance	>		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights		~	
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3		
Central locking		~	
Remote locking			~
Sat. Nav. (basic test only)			~
Reversing camera			1

I have read and understood this condition guide.

Name:

Signature: