

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Coolant condition Performance SC Key: Radiator / Hoses (visual) S = scratchTransmission D = dent S S SC Operation R = rustNoise PT = paint defect C = crackClutch P = pin dent CV joints S SC * = decals Wheel bearings SC = stone chips Brakes W = significant scuffs S Performance Hand Brake Note: some defects & blemishes may not be displayed in the diagram

Body Inspection C	omments	Tidilu Diake		
		Tyres (lowest observed tread depth of tyres)		
		Left front	5	mm
		Right front	5	mm
		Left rear	5	mm
Conditions During Body Inspection: Dry		Right rear	5	mm
		Spare	Yes	
Under Carriage & Under Bonnet Inspection Comments		Suspension		
		Suspension performance	~	
		Steering performance	~	
		Shock absorbers	~	
		Air Conditioning / Heater	ing / Heater	
_		Operation	~	
Interior Comments		Electrical / Accessories		
Seats	minor stains ,wear and tear ,	Head lights	~	
Correcto	Good	Tail lights	~	
Carpets		Indicators	~	
Panels	Good	Dashboard warning lights	~	
	Good	Wipers (front & rear)	~	
Dashboard		Window winder FL	~	
		Window winder FR	~	
General Comment	<u>2:</u>	Window winder RL	~	
		Window winder RR	~	
		Rear view mirrors	~	
		Radio (basic test only)	~	
		CD (basic test only)	~	
		Number of keys	2	
Road Conditions During Test Drive: Dry		Central locking	~	
E . E		Remote locking	~	
Engine Timing Mechanism: Cambelt		Sat. Nav. (basic test only)		~
Evidence of Cam B	elt Replacement: No Kms:	Reversing camera	~	
Inspected by: Dor	Date: 28 Jun 2017			
have read and unde	erstood this condition guide. Name:	Signature:		

Pass

V

V

V

V

V

V

V

V

V

V

V

V

. .

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Fail

N/A

V