

Basic Vehicle Condition Guide

Report ID: 16,532,034


Version: 2

Created: 06 Jul 2017

Make: Model: Mazda Capella **Body Style:** Wagon Year: 1,997 Registration: Reg Expiry: 05 Oct 2017 **DQU581** WoF Expiry: **Odometer:** 08 Sep 2017 **Good No:** 16532034 207,726 Kms VIN: 7A8C10R0705315961 **Next Service: Service History:** 210000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

LHR tail light broken also same side light on the tail gate ,RF door missing a moulding around the frame ,

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak, minor surface rust under body,

| Interior Comments | | | |
|-------------------|------------------------------|--|--|
| Seats | wear and tear,minor stains | | |
| Carpets | wear and tear,minor stains , | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 181,644

Inspected by: Donovan Matara Date: 06 Jul 2017

| | Pass | Fail | N/A |
|------------------------------|------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | v v | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | <i>v v</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | • | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | | 4 | mm |
| Right front | 4 | 4 | mm |
| Left rear | 3 | | mm |
| Right rear | 4 | | mm |
| Spare | | Yes | |
| Suspension | • | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | | ~ | |
| Electrical / Accessories | • | • | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | v | | |
| Wipers (front & rear) | | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | • |
| Central locking | ~ | | |
| Remote locking | | | ~ |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| • | | | |

I have read and understood this condition guide.

Name:

Signature: