

Report ID: 16,534,048


Version:

04 Jul 2017 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Sedan
Year:	2,002	Registration:	DUK945	Reg Expiry:	20 Jul 2017
WoF Expiry:	23 Jun 2018	Odometer:	233,323 Kms	Good No:	16534048
VIN:	7A8C1390707106415	Next Service:	213142	Service Histor	'y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Missing badge off tail gate, clear coat coming off the roof,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Commen	<u>ts</u>
Seats	wear and tear,minor stains,drivers seat small rip.
Carpets	wear and tear,minor stains ,
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

04 Jul 2017 Inspected by: Donovan Matara Date:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	V V V		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	V		
Hand Brake			V
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		3	mm
Right front	4		mm
Left rear	5		mm
Right rear	5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		V	
Electrical / Accessories		<u> </u>	
Head lights	~		
Tail lights			
Indicators	~		
Dashboard warning lights	<i>'</i>		
Wipers (front & rear)	\(\times \)		
Window winder FL			
Window winder FR	V		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	\(\times \)		
			-
Radio (basic test only)	<i>'</i>		
CD (basic test only) Number of keys	1		
·	1		1
Central locking	<i>V</i>		
Remote locking	\ <u>'</u>		_
Sat. Nav. (basic test only)			'
Reversing camera			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \

I have read and understood this condition guide.

Name:

Signature: