

Report ID: 16,537,118 Version: 2 Created: 02 Feb 2018

Make:	Volkswagen	Model:	Beetle	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,011	Registration:	FYR205	Reg Expiry:	05 Oct 2017	Engine	1		
WoF Expiry:	27 Oct 2017	Odometer:	47,289 Kms	Good No:	16537118	Oil level	~		
VIN:	WVWZZZ9CZAM0141	Next Service:	62000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				710	HIV	Operation	~		
PT = paint def		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74 <u>11</u> 4	CV joints	~		
* = decals	sc 916			To .		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body inspection comments						Tyres (lowest observed trea	d depth	of tyre	<u> </u>
						Left front	5.	.0	mm
						Right front	5.		mm
						Left rear	6.		mm
Conditions During Body Inspection: Dry						Right rear	6		mm
						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Dry						Central locking	· ·		
			Dry			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
L	-	-							
Inspected by: Donovan Matara						Date: 26 Jul 201	7		
I have read	and understood th	is condition c	juide. Name: .			Signature:			