

Basic Vehicle Condition Guide


Report ID: 16,590,882

Version: 2

Make: Model: Honda AIR **Body Style:** SUV Year: 2,005 Registration: HEW925 Reg Expiry: 17 Dec 2017 WoF Expiry: **Odometer: Good No:** 21 Jun 2018 16590882 140,977 Kms VIN: 7AT08GBNX13002562 **Next Service: Service History:** 146631

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Re align LHF bumper,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	wear and tear,minor stains .	
Carpets	wear and tear,minor stains .	
Panels	Good	
Dashboard	Good	

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Inspected by: Donovan Matara

Pass V V V V V V V V V V V V V V V V V V	Fail	N/A
<i>y y</i>		· · · · · · · · · · · · · · · · · · ·
<i>y y</i>		v
'		v
'		~
V V V V V V V V V V V V V V V V V V V		· · · · · · · · · · · · · · · · · · ·
V V V V V V V V V V V V V V V V V V V		~
ン ン ン ン ン ン ン ン ン ン		·
ンンンンンンン		v
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		v
\ \ \ \ \		V
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		~
\ \ \ \		'
<i>y y y</i>		'
v v		
v v		
V		
V		
•		
~		
depth	of tyre	25)
	-	mm
	-	mm
	-	mm
		mm
	103	
/		
· ·		
· ·		
<u> </u>		
/		
_		
./		
./		
_		
•		.,
		'
		V
	3	

I have read and understood this condition guide. Name: Signature: