

Report ID: 16,591,143 Version: 1 26 Jul 2017 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2,011	Registration:	HMR682	Reg Expiry:	20 Jan 2018	Engine			1
WoF Expiry:		Odometer:	128,811 Kms	Good No:	16591143	Oil level	~		
VIN:	KL3CD26CJBB057872	Next Service:	138800	Service Histor		Smoke & fumes	~		
					,	Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		<u> </u>
						Performance	~		
Key:	sc	-0				Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			XXX	Transmission	•		
D = dent	s sc			The	EI SD	Operation	~		
R = rust				10	THIA	Noise	~		-
PT = paint def C = crack						Clutch			~
P = pin dent	Ho	KI			JUII ——	CV joints	~		
* = decals	s sc pp			AL-	ENR -	Wheel bearings	-		
SC = stone chips						<u>_</u>	~		
W = significant scuffs						Brakes			
		Nata				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<i>с</i> .	
RF light in mirror						Tyres (lowest observed tread depth of tyres)			
						Left front	6	5	mm
						Right front		5	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	5	5	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & Under BOI	inet inspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Nav screen	N/W,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		~	1
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera		~	1
						L	1		
Inspected by: Donovan Matara Date: 26 Jul 2017									
I have read and understood this condition guide. Name:									