

Report ID: 16,591,664 Version: 3 18 Oct 2017 Created:

Make:	Subaru	Model:	Outback	Body Style:	SUV]		Pass	Fail	N/A	
Year:	2,012	Registration:	GJP108	Reg Expiry:	15 Aug 2017		Engine			•	
WoF Expiry:	08 Feb 2018	Odometer:	228,171 Kms	Good No:	16591664		Oil level	~			
VIN:	JF2BR9K95CG036308	Next Service:	230000	Service Histor	y: No		Smoke & fumes	~			
						1	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Н	Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	harge.		Coolant condition	~			
						1	Performance	~			
Key:		-0	S S	-01-			Radiator / Hoses (visual)	~			
S = scratch							Transmission				
D = dent R = rurt							Operation	~			
R = rust PT = paint defect							Noise	v			
C = crack				$+ \mathbf{\nabla}$	R		Clutch	-		~	
P = pin dent					세비		CV joints	~			
* = decals	sc 916		<u> </u>	The	EITPS		Wheel bearings	~			
SC = stone chips							Brakes	•			
W = significant scuffs							Performance	~			
		Note: son		may not be disc	laved in the diagram		Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Tyres (lowest observed tread	•	oftyre	 >\$)	
Stone chip on front windscreen											
							Right front		4		
							Left rear		4	mm	
						1			5	mm	
Conditions During Body Inspection: Dry]	Right rear 6 mm				
Under Carriage & Under Bonnet Inspection Comments						1	Spare Yes Yes				
	inage a onder bor	meenspeede	<u>on comments</u>				•			-	
							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
Interior Comments							Operation	~			
Good							Electrical / Accessories				
Seats							Head lights	~			
Carpets	Good						Tail lights	~			
	Good						Indicators	~			
Panels	Guou						Dashboard warning lights	~			
Dashboa	rd Good						Wipers (front & rear)	~			
						J	Window winder FL	~			
Canada						٦l	Window winder FR	~			
General Comments Four wheel drive							Window winder RL	~			
Four wheel	unve						Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						1	Number of keys	1			
Road Conditions During Test Drive: Dry							Central locking	~			
							Remote locking	~			
Engine Timing Mechanism: Cambelt							Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	10	Kms:		J	Reversing camera	~			
Inspected by: Bobby Zhong							Data: 10.0-# 201	7			
Inspected by: Bobby Zhong Date: 18 Oct 2017											

I have read and understood this condition guide.

Name:

Signature: