

Report ID: 16,593,397 Version: 2 Created: 20 Jul 2017

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,014	Registration:	KQD884	Reg Expiry:	30 Jan 2018	Engine	I	1	
WoF Expiry:	•	Odometer:	52,948 Kms	Good No:	16593397	Oil level	~		
VIN:	WBA3D36090NS4513	Next Service:	,	Service Histor		Smoke & fumes	~		
			-			Performance	~		
	port is not a warranty	unting is uppede	for one and miles as	Danta hava nat	hoon dismonthed on	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent	- Glb			The	EIU/	Operation	~		1
R = rust PT = paint def				\prod		Noise	~		
C = crack				+		Clutch			~
P = pin dent						CV joints	~		
* = decals	- PIK			AL.	ENR	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs						Performance	~		1
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	ofture))
						Left front	· ·		
								3	mm
						Right front		3	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	inet inspectio	on comments			Suspension	L .		1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			1
Seats	dood					Head lights	~		
Carpets	Good					Tail lights	~		
carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		1
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		1
						L		1	
Inspecte	d by: Donovan Matar	Date: 20 Jul 201	7						
I have read	and understood th	is condition c	uide. Name:			Signature:			