

I have read and understood this condition guide.

Report ID: 16,596,105 Version: 1 Created: 27 Jul 2017

Signature: .....

| Make:  | Hyundai                  | Model:         | Santa FE               | Body Style:       | SUV                  |  | Pass | Fail           | N/A |
|--|--------------------------|----------------|------------------------|-------------------|----------------------|--|------|----------------|-----|
| Year:  | 2,013                    | Registration:  | HCY622                 | Reg Expiry:       | 22 Oct 2017          | Engine                                       |      |                | I   |
| WoF Expiry:  | 2,013<br>26 Jul 2018     | Odometer:      | 182,552 Kms            | Good No:          | 16596105             | Oil level                                    | ~    |                |     |
| VIN:   | KMHST81XSEU223336        | Next Service:  | 194000                 | Service Histor    |                      | Smoke & fumes                                | ~    |                |     |
|  |                          |                |                        |                   |                      | Performance                                  | ~    |                |     |
|  | port is not a warranty   |                | 6                      | Danta have a st   |                      | Noise  | ~    |                |     |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends |                          |                |                        |                   |                      | Cooling System                               |      |                |     |
|  | ical inspection prior to |                |                        |                   |                      | Coolant condition                            | ~    |                |     |
|  |                          |                |                        |                   |                      | Performance                                  | ~    |                |     |
| Key:   | sc                       | -0             | S S                    |                   |                      | Radiator / Hoses (visual)                    | ~    |                |     |
| S = scratch  |                          |                |                        |                   |                      | Transmission                                 |      |                |     |
| D = dent   | s sc                     |                |                        | The               |                      | Operation                                    | ~    |                |     |
| R = rust   |                          |                |                        | 10                | JHIH                 | Noise  | ~    |                |     |
| PT = paint def<br>C = crack  |                          |                |                        | +                 | D SC                 | Clutch                                       | •    |                | ~   |
| P = pin dent   |                          |                |                        |                   |                      | CV joints                                    | ~    |                | •   |
| * = decals   | SPSC PIC                 |                |                        | AL.               | EIIP I               | Wheel bearings                               | ~    |                |     |
| SC = stone chips   |                          |                |                        |                   |                      | Brakes                                       |      |                |     |
| W = significant scuffs   |                          |                |                        |                   |                      | Performance                                  |      |                |     |
|  |                          | Note: com      | ne defects & blemishes |                   | layed in the diagram | Hand Brake                                   |      |                |     |
|  | pection Comments         |                |                        | illay not be disp | hayed in the diagram |  |      | - <b>f h</b> m |     |
| Aerial attached to the LF guard ,LF door mirror stone chips,   |                          |                |                        |                   |                      | Tyres (lowest observed tread depth of tyres) |      |                |     |
|  |                          |                |                        |                   |                      | Left front                                   | 6    |                | mm  |
|  |                          |                |                        |                   |                      | Right front                                  | 6    |                | mm  |
|  |                          |                |                        |                   |                      | Left rear                                    | e    |                | mm  |
| Conditions During Body Inspection: Dry   |                          |                |                        |                   |                      | Right rear                                   |      |                |     |
| Under Carriage & Under Bonnet Inspection Comments  |                          |                |                        |                   |                      | Spare Yes                                    |      |                |     |
|  | inage & onder bor        | inet inspectic | <u>on comments</u>     |                   |                      | Suspension                                   |      |                |     |
|  |                          |                |                        |                   |                      | Suspension performance                       | ~    |                |     |
|  |                          |                |                        |                   |                      | Steering performance                         | ~    |                |     |
|  |                          |                |                        |                   |                      | Shock absorbers                              | ~    |                |     |
|  |                          |                |                        |                   |                      | Air Conditioning / Heater                    |      |                |     |
| Interior Comments  |                          |                |                        |                   |                      | Operation 🖌                                  |      |                |     |
| Good   |                          |                |                        |                   |                      | Electrical / Accessories                     |      |                |     |
| Seats  | duod                     |                |                        |                   |                      | Head lights                                  | ~    |                |     |
| Carpets  | Good                     |                |                        |                   |                      | Tail lights                                  | ~    |                |     |
|  | Card                     |                |                        |                   |                      | Indicators                                   | ~    |                |     |
| Panels   | Good                     |                |                        |                   |                      | Dashboard warning lights                     | ~    |                |     |
| Dashboa  | Good                     |                |                        |                   |                      | Wipers (front & rear)                        | ~    |                |     |
|  |                          |                |                        |                   |                      | Window winder FL                             | ~    |                |     |
|  |                          |                |                        |                   |                      | Window winder FR                             | ~    |                |     |
| General C  | <u>Comments</u>          |                |                        |                   |                      | Window winder RL                             | ~    |                |     |
|  |                          |                |                        |                   |                      | Window winder RR                             | ~    |                |     |
|  |                          |                |                        |                   |                      | Rear view mirrors                            | ~    |                |     |
|  |                          |                |                        |                   |                      | Radio (basic test only)                      | ~    |                |     |
|  |                          |                |                        |                   |                      | CD (basic test only)                         | ~    |                |     |
|  |                          |                |                        |                   |                      | Number of keys                               | 2    |                |     |
| Road Con   | Central locking          | ~              |                        |                   |                      |  |      |                |     |
|  |                          |                | Dry                    |                   |                      | Remote locking                               | ~    |                |     |
| Engine Timing Mechanism: Timing Chain  |                          |                |                        |                   |                      | Sat. Nav. (basic test only)                  |      |                | ~   |
| Evidence   | of Cam Belt Replac       | ement: N       | lot Applicable         | Kms:              |                      | Reversing camera                             |      |                | ~   |
| Inspected by Depayan Mataza  |                          |                |                        |                   |                      |  |      |                |     |
| Inspected by: Donovan Matara Date: 27 Jul 2017   |                          |                |                        |                   |                      |  |      |                |     |
|  |                          |                |                        |                   |                      |  |      |                |     |

Name: .....