

Basic Vehicle Condition Guide

Report ID: 16,598,887


Version: 3

Created: 15 Aug 2017

Make: Model: Mitsubishi L300 **Body Style:** Van Year: 2,013 Registration: HBQ743 Reg Expiry: 08 Nov 2017 WoF Expiry: **Odometer:** 30 Sep 2017 **Good No:** 16598887 193,503 Kms VIN: JMAHNP14VDA80073 **Next Service: Service History:** 109142

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RF head light broken ,RR tail light broken.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak.

Interior Comment	<u>S</u>
Seats	drivers seat ripped, wear and tear, stains
Carpets	drivers floor ripped ,
Panels	Average
Dashboard	Average

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\triangle \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	\(\times \)			
Clutch	~			
CV joints	~			
Wheel bearings	~			
Brakes	•		•	
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	3.0		mm	
Right front	4.0		mm	
Left rear	3.0		mm	
Right rear	4.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
	<i>v</i>			
Suspension performance	\(\times \)			
Suspension performance Steering performance	<i>V V</i>			
Suspension performance Steering performance Shock absorbers	<i>V V</i>	·		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater	V V	V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation	V V V	V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories	·	·		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights	·	V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights	·	<i>V</i>		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators	·	V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights	V V V V V V V V	V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear)	·	V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL	·	V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR	·	<i>y</i>		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL	·			
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR	·			
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	·		V V	
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only)	·			
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V V V V V V	V V V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	V V V V V V V V	V V V		
Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	V V V V V V V V			

I have read and understood this condition guide.

Donovan Matara

Name:

Signature:

14 Jul 2017

Reversing camera