

Report ID: 16,604,132 Version: 1 20 Jul 2017 Created:

Make:	Ssangyong	Model:	Musso	Body Style:	Utility		Pass	Fail	N/A
Year:	2,005	<b>Registration:</b>	CUE327	<b>Reg Expiry:</b>	11 Jul 2017	Engine			•
WoF Expiry:	09 Feb 2018	Odometer:	418,996 Kms	Good No:	16604132	Oil level	~		
VIN:	KPAWA2EDS5P39616	Next Service:	436300	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SD	-0		-01-	<u>SD</u>	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S C S D R						Operation	~		
PT = paint defect						Noise	~		
C = crack				+	S SC	Clutch	-		~
P = pin dent					게비	CV joints	~		•
* = decals	SDSC 916			- No	<b>HIP</b>	Wheel bearings	v		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	e defects & blemishes	s may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	of tyre	() ()
Clear coat coming off RF ,LF door mirrors ,canopy needs paint,					Left front 3 mm				
						Right front			mm
						Left rear		3	mm
									-
Conditions During Body Inspection: Wet									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
							~		
Steering performance Shock absorbers							-		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation Electrical / Accessories		~	
wear and tear minor stains									
Seats						Head lights	~		
Carpets	wear and t	ear,minor stains	,			Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	Comments					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
- Engine Ti	ning Mechanism	الما				Remote locking			~
Engine Timing Mechanism: Unknown Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 20 Jul 2017									

I have read and understood this condition guide.

Name: .....

Signature: .....