

Report ID: 16,623,571 Version: 1 10 Aug 2017 Created:

Make:									
	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
/ear:	2,012	Registration:		Reg Expiry:	19 Nov 2017	Engine	1		1
VoF Expiry:		Odometer:	214,305 Kms	Good No:	16623571	Oil level	~		
/IN:	MM0UP0YF10012691	Next Service:	213000	Service Histor	y: No	Smoke & fumes	~		
Note: This re	port is not a warranty					Performance	~		
This report is	s a guide only. Conside					Noise	~		
	sting undertaken. The vinical inspection prior to					Cooling System			
	··· · · · · · · · · · · · · · · · · ·	F	J			Coolant condition	~		
Key:	S SC	\sim	S SC S SC		S D SC	Performance	~		
= scratch		\sim (O)		5(O)-		Radiator / Hoses (visual)	~		
) = dent					100	Transmission			
= rust	SDSC 96			-10		Operation	~		
T = paint def	ect NP	1				Noise	~		
= crack						Clutch	~		
e pin dent	ssc dle			-	241 <u>16</u>	CV joints	~		
= decals		10		10	SD SD	Wheel bearings	~		
C = stone chi V = significan	7	۳ (Q)		$\forall (Q)$	×	Brakes			
v – signinean	S SC		S SC		S SC	Performance	~		
Body Insr	nection Comments	Note: son	ne defects & blemish	es may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Front bumper flakey paint screw holes ,LH sill dented, aerial stuck to LF guard ,						Tyres (lowest observed tread depth of tyres)			
i ioni buinț				guara,		Left front	4	1	mm
						Right front	4	1	mm
						Left rear		3	mn
Conditions During Body Inspection: Wet						Right rear		3	mn
						Spare		Yes	
<u>Under Ca</u>	arriage & Under Bor	nnet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Suspension performance Steering performance	レ レ		
							-		
						Steering performance Shock absorbers	~		
						Steering performance	~		
Interior C	<u>Comments</u>					Steering performance Shock absorbers Air Conditioning / Heater	v v		
		tear,minor stains				Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories	· ·		
Interior C Seats	wear and t	tear,minor stains				Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights	v v		
		tear,minor stains				Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights	V V V V V V V		
Seats Carpets	wear and t	tear,minor stains				Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicators			
Seats	Good Good	tear,minor stains				Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights	V V V V V V V		
Seats Carpets	Good Good	tear,minor stains				Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)	V V V V V V V V V V V V V V V		
Seats Carpets Panels	Good Good	tear,minor stains	· · · · · · · · · · · · · · · · · · ·			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FL	V V		
Seats Carpets Panels Dashboa	Good Good	tear,minor stains	;, 			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FR	V V		
Seats Carpets Panels Dashboa	Good Good Good ard	tear,minor stains	· · · · · · · · · · · · · · · · · · ·			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RL	V V		
Seats Carpets Panels Dashboa	Good Good Good ard	tear,minor stains	· ,			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RLWindow winder RR	V V		
Seats Carpets Panels Dashboa	Good Good Good ard	tear,minor stains	;, 			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RRRear view mirrors	V V		
Seats Carpets Panels Dashboa	Good Good Good ard	tear,minor stains	· · · · · · · · · · · · · · · · · · ·			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RRRear view mirrorsRadio (basic test only)	V V		
Seats Carpets Panels Dashboa	Good Good Good ard	tear,minor stains	· ,			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)	V V		
Seats Carpets Panels Dashboa	wear and t Good Good ard Comments					Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keys	V 2		
Seats Carpets Panels Dashboa	Good Good Good ard		., 			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keysCentral locking	V V		
Seats Carpets Panels Dashboa General (Road Con	wear and t Good Good ard <u>Good</u> <u>Good</u> <u>Comments</u>	t Drive:	Wet			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keysCentral lockingRemote locking	V 2		
Seats Carpets Panels Dashboa General C Road Con Engine Tin	wear and t Good Good ard Comments Comments Ming Mechanism:	t Drive:	Wet			Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keysCentral lockingRemote lockingSat. Nav. (basic test only)	V V		
Seats Carpets Panels Dashboa General C Road Con Engine Tin	wear and t Good Good ard <u>Good</u> <u>Good</u> <u>Comments</u>	t Drive:	Wet	Kms:		Steering performanceShock absorbersAir Conditioning / HeaterOperationElectrical / AccessoriesHead lightsTail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keysCentral lockingRemote locking	V V		

I have read and understood this condition guide.

Name:

Signature: