

Basic Vehicle Condition Guide

Report ID: 16,631,009

Version: 3

Created: 04 Dec 2017

Pass


N/A

Fail

Make: Model: Volkswagen Polo **Body Style:** Hatchback Year: Registration: Reg Expiry: 2,000 EAY421 04 Sep 2017 WoF Expiry: **Odometer: Good No:** 16631009 28 Jul 2018 151,301 Kms VIN: WVWZZZ6NZ1D00289 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Head lamps faded Wiper blades need replacement Front LHS power window stuck

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Both sill dent

Rear suspension needs attention

Exhaust leak

Interior	Comments
IIIICIIOI	Commencia

Seats	Good
Carpets	Average
Panels	RH front door panel& roof lining need attention
Dashboard	Good

General Comments

Central locking not working Gear lever slide cover damaged Fuse box cover missing LHS fender indicator cover missing

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Eligilie			
Oil level	~		
Smoke & fumes	V		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyr	es)
Left front		3	mm
Right front	3		mm
Left rear	3 mm		
Right rear	2 mr		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers		~	
Air Conditioning / Heater	ı	ı	1
Operation	~		
Electrical / Accessories		1	
Head lights	~		
Tail lights		~	
Indicators		~	
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR		~	
Window winder RL			V
Window winder RR			V
Rear view mirrors	~		1
Radio (basic test only)	~		
CD (basic test only)			V
Number of keys	2	1	1
Central locking		~	
Remote locking			V
Sat Nay (basic test only)			1./

Inspected by: Mathew Varghese

I have read and understood this condition guide.

Name:

Signature:

04 Dec 2017

1

Reversing camera