

Basic Vehicle Condition Guide

Report ID: 16,636,537


Version:

Created: 22 Aug 2017

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2,013 Registration: GYU980 Reg Expiry: 15 Oct 2017 Good No: **WoF Expiry: Odometer:** 28 Aug 2018 169,988 Kms 16636537 VIN: KMHST81XSDU16337; Next Service: **Service History:** 182208 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Aerial attached to the LF guard,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------------------------------|--|--|
| Seats | wear and tear,minor stains , | | |
| Carpets | wear and tear,minor stains , | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara

Name:

| - Create | | - / (0.9 - | |
|------------------------------|-----------------|------------|----------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\triangle \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | • | | • |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 5 | | mm |
| Right front | 6 | | mm |
| Left rear | 5 | | mm |
| Right rear | 6 | | mm |
| Spare | Ye | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ı | | 1 |
| Operation | ~ | | |
| Electrical / Accessories | | | I |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | 1 |
| Central locking | · | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| | I | | <u> </u> |
| Reversing camera | ~ | | |

22 Aug 2017

Signature:

Date: