

Report ID: 16,639,099 Version: 1 Created: 13 Sep 2017

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,005	Registration:	CZM494	Reg Expiry:	21 Oct 2017	Engine			
WoF Expiry:	16 Feb 2018	Odometer:	292,789 Kms	Good No:	16639099	Oil level	~		
VIN:	JM0BK10F100172523	Next Service:	293000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and miloago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC S	-0	S D			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIN		Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack				+	SC	Clutch	-		~
P = pin dent	HIC				세비	CV joints	~		•
* = decals	ssc 91			- Jul	ELL'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S S S S S S S S S S S S S S S S						Performance	~		
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments							es (lowest observed tread depth of tyr		es)
Clear coat coming off RR guard ,both headlight covers have surface cracks on them ,						Left front 5 mm			
						Right front			mm
						Left rear			mm
Conditions During Pody Inspection:						Right rear	4 mm 3 mm		
Conditions During Body Inspection: Dry						Spare	-		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats wear and tear,minor stains ,						Head lights	~		
Seals						Tail lights	~		
Carpets	wear and t	tear,minor stains	,				~		
	Good						-		
Panels						Dashboard warning lights Wipers (front & rear)	v		
Dashboa	rd Good					Window winder FL	v		
						Window winder FL Window winder FR	v		
General (Comments					Window winder FR Window winder RL	v		
							~		
						Window winder RR Rear view mirrors	~		
							~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
Engine Tir	ming Mechanism:	Timina	Chain			Remote locking	~		
Evidence of Cam Bolt Donlacement:									~
			lot Applicable	11113.		Reversing camera			~
Inspected by: Donovan Matara Date: 13 Sep 2017									

I have read and understood this condition guide.

Name:

Signature: