

Report ID: 16,640,582 Version: 1 Created: 08 Aug 2017

Make:	Mitsubishi	Model:	Airtrek	Body Style:	SUV		Pass	Fail	N/A
Year:	2,001	Registration:	DLW209	Reg Expiry:	14 Aug 2017	Engine			
WoF Expiry:	24 Aug 2017	Odometer:	233,541 Kms	Good No:	16640582	Oil level	~		
VIN:	7A8CJ3F0706004705	Next Service:	222100	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	~		
Key:	SD	-0	SD SD		S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SD 6			The	BID SD	Operation	~		<u> </u>
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect M			+	D	Clutch			~
P = pin dent	Htc	KI			JUII —	CV joints	~		
* = decals	SDSC PR			AL-	Elipe s		-		
SC = stone chi	ps U	20		A		Wheel bearings Brakes	~		
W = significant scuffs S SC S S S S S S S S S S S S S S S S S									<u> </u>
		Nata				Performance	~		<u> </u>
Body Ins	pection Comments	Note: som	ne defects & blemishes	may not be disp	hayed in the diagram	Hand Brake		<u> </u>	Ļ
Moisture inside the RF head light ,						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
						Spare	105		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak ,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
	· · · · · · · · · · · · · · · · · · ·					Operation		~	
Interior Comments front seats and console lid vinyl cracked, stains ,						Electrical / Accessories		-	
Seats	front seats	s and console lid	vinyl cracked, stains ,			Head lights	~		
Carpote	wear and	tear,minor stains	1			Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
	_					Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		·
Road Con	Central locking	~							
	-		Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 21	2,100	Reversing camera			~
Inspected by: Donovan Matara Date: 08 Aug 2017									

I have read and understood this condition guide.

Name:

Signature: