

Report ID: 16,652,174 Version: 1 15 Aug 2017 Created:

Make:	Daihatsu	Model:	YRV	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,005	Registration:	EZW239	Reg Expiry:	15 Oct 2017	Engine			L
WoF Expiry:	06 Jul 2018	Odometer:	21,001 Kms	Good No:	16652174	Oil level	~		
VIN:	7A8471Y0709023463	Next Service:	30000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	V		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	V		
Key:	SC	-0	L S SC		s	Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission	Transmission		
D = dent R = rust	s sc			715	HILS	Operation	V		
PT = paint defe	ect NP	F I		$\left( \left  \right\rangle \right)$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HIG				74 <u>11</u> 4	CV joints	~		
* = decals	ssc 916			To .	FID SSC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S SC		S P SC S P SC			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front	5	5	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashhaa	Good					Wipers (front & rear)	~		
Dashboa	Ira					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Enging Ti	ming Mechanism	T:	Chain			Remote locking			~
Engine Timing Mechanism: Timing Chain   Evidence of Cam Belt Replacement: Not Applicable Kms:   Beversing camera									~
Evidence		ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 15 Aug 2017									

I have read and understood this condition guide.

Name: .....

Signature: .....