

## **Basic Vehicle Condition Guide**

Report ID: 16,653,197


Version:

Created: 13 Sep 2017

Make: Model: Golf **Body Style:** Hatchback Volkswagen Year: Registration: **Reg Expiry:** 2,006 DKL2 31 Jul 2018 **WoF Expiry: Odometer: Good No:** 18 Aug 2018 163,983 Kms 16653197 VIN: **Next Service: Service History:** WVWZZZ1KZ6U02973 173950 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>	
Seats	wear and tear,minor stains ,
Carpets	wear and tear,minor stains ,
Panels	hood lining coming off ,
Dashboard	Average

## **General Comments**

Inspected by:

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No

Kms:

Fail N/A **Pass** Engine Oil level Smoke & fumes 1 Performance / Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm 6 Left rear 5 mm Right rear  $\mathsf{mm}$ 6 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~

I have read and understood this condition guide.

Donovan Matara

Name: .....

Signature: .....

13 Sep 2017

1

Reversing camera

Date: