

Report ID: 16,660,689 Version: 2 14 Sep 2017 Created:

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2,013	Registration:	HDL643	Reg Expiry:	01 Jun 2018	Engine			L	
WoF Expiry:	27 Jan 2018	Odometer:	114,412 Kms	Good No:	16660689	Oil level	~			
VIN:	6G1PD5E8XEL929368	Next Service:	125300	Service Histor	V: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:		-0	SC		s	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	sc d			215	HIV	Operation	~			
PT = paint defe				$\left[\left(\right) \right]$		Noise	~			
C = crack					S SC	Clutch			~	
P = pin dent	HIP				74 <u>11</u> 4	CV joints	~			
* = decals	ssc 91			The second		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
w = significant					SC	Performance	~			
Body Incr	ection Comments	Note: som	e defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments LF door mirror scratched ,						Tyres (lowest observed tread	l depth	of tyre	es)	
						Left front	Left front 4 n			
						Right front	4		mm	
						Left rear	4		mm	
Conditions During Body Inspection: Dry						Right rear			mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
			_			Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inchasta	Inspected by: Donovan Matara Date: 14 Sep 2017									
Inspected	a by. Donovan watar					Date. 14 Sep 20	. /			

I have read and understood this condition guide.

Name:

Signature: