

Report ID: 16,660,834 Version: 1 12 Sep 2017 Created:

Make:	Mercedes-Benz	Model:	Vito	Body Style:	People Mover		Pass	Fail	N/A
Year:	2,008	Registration:	EOY751	Reg Expiry:	24 Sep 2017	Engine	1 435	1 dii	
NoF Expiry:	2,008 31 Aug 2018	Odometer:		Good No:	16660834	Oil level	~		<u> </u>
/IN:	WDF63960323440019		225,232 Kms	Service Histor		Smoke & fumes	~		
/	WDF63960323440019	NEXT SEIVICE.	235200	Service mistor	/: No	l			
	port is not a warranty					Performance	~		-
This report is	a guide only. Consid sting undertaken. The	eration is made	for age and milea	ge. Parts have not	been dismantled or	Noise	~		
	ical inspection prior to					Cooling System			
					-	Coolant condition	~		
Key:			SC			Performance	~		
= scratch	-	$\sim$ $(O)$		$ \leq (0) $	$\checkmark$	Radiator / Hoses (visual)	~		
0 = dent					BI SDC	Transmission			
= rust	s sc				HIL	Operation	~		
PT = paint def	ect N	1				Noise	~		
2 = crack						Clutch			~
e pin dent	ssc dk			-	74HLb	CV joints	~		
= decals		10		10		Wheel bearings	٢		
C = stone chi V = significan	7	$\underline{(0)}$		Z(Q)	R	Brakes			
	SC S	C		S		Performance	~		
Body Insi	pection Comments	Note: son	ne defects & blemisł	nes may not be disp	layed in the diagram	Hand Brake	~		
<u>body ms</u>						Tyres (lowest observed trea	d depth	of tyre	es)
						Left front	6	3	mn
						Right front	8	3	mn
						Left rear	8		mr
Conditions During Body Inspection: Wet						Right rear	8		mn
Conditions During Body Inspection: Wet						Spare	Yes		
<u>Under Ca</u>	rriage & Under Bo	nnet Inspectio	on Comments			Suspension		103	
	-					Suspension performance	~		1
						Steering performance	~		+
						Shock absorbers	~		
						Air Conditioning / Heater	V		
									T
Interior Comments						Operation Electrical / Accessories	~		
	minor sta	ns ,							T
Seats		-				Head lights	~		+
Carpets	Good					Tail lights	~		
	Good					Indicators	~		+
Panels	3000					Dashboard warning lights	~		_
Dashboa	rd Good					Wipers (front & rear)	~		_
						Window winder FL	~		
						Window winder FR	~		
General (	<u>Comments</u>					Window winder RL			V
						Window winder RR			V
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	<		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Unknow	/n			Sat. Nav. (basic test only)			V
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
									_
Inspecte	d by: Donovan Matai	2				Date: 12 Sep 20	17		

I have read and understood this condition guide.

Name: .....

Signature: .....