

Report ID: 16,662,666 Version: 2 Created: 05 Sep 2017

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,007	Registration:	GMK408	Reg Expiry:	19 Aug 2017	Engine	1		L
WoF Expiry:	03 May 2018	Odometer:	178,777 Kms	Good No:	16662666	Oil level	~		
VIN:	7AT0GF09X12002871	Next Service:	156000	Service Histor	V: No	Smoke & fumes	V		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	r		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	LIS	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = sust SC B B S S						Operation	~		
R = rust PT = paint def				\prod	JHH	Noise	~		
PT = paint defect C = crack						Clutch	~		
P = pin dent						CV joints	~		
*=decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
		Note: con	e defects & blemisbes		laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
Front park light not working Number plate light not working						Tyres (lowest observed tread depth of tyres)			
Front bumper lip cracked						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder bor	mermspectic	<u>on comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	arm rest b	roken				Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		_
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Bobby Zhong Date: 28 Aug 2017									
I have read and understood this condition guide. Name:									