

Report ID: 16,665,261 Version: 1 Created: 14 Sep 2017

Make:	Holden	Model:	Commodore	Body Style:	Sedan	1Г		Pass	Fail	N/A
Year:	2,005	Registration:	EKW505	Reg Expiry:	21 Sep 2017	E	ngine		i	1
WoF Expiry:		Odometer:	239,758 Kms	Good No:	16665261	୲⊢	Oil level	~		
VIN:	6G1ZK54B75L379204	Next Service:		Service Histor	y: No		Smoke & fumes	~		
						it	Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						lc	Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional of	charge.		Coolant condition	~		
	S D PT SC S				S P SC	۱Ľ	Performance	~		
Key:	SUPISCIES	$-\infty$	s s	50 ⁵	SPSC		Radiator / Hoses (visual)	~		
S = scratch D = dent						Т	ransmission			1
R = rust	SD DA			710	HI SD		Operation	~		
PT = paint defe	ect NP	r I		$\left(\left \left(\right) \right\rangle \right)$	7014		Noise	~		
C = crack							Clutch			~
P = pin dent	HIG				74114		CV joints	~		
* = decals	S D PT SC 91			-No-	ALD S		Wheel bearings	~		
SC = stone chips						В	Brakes			
W = significant scuffs S D P SC S S D S D S D S D S D							Performance	~		
Podulaci	action Commonts	Note: son	ne defects & blemishes	s may not be disp	played in the diagram		Hand Brake	~		
Body inspection comments						Т	yres (lowest observed tread	l depth	of tyre	es)
Clear coat coming off bonnet ,RF guard,LF guard ,cover missing front bumper ,							Left front 4 mm			
							Right front	4		mm
						┟┝	Left rear		3 m	
Conditions During Body Inspection: Wet						۱ŀ	Right rear	3		mm
Conditions During Body Inspection: Wet						╧┝	Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						1 -	Suspension			
Minor oil le	ak,						Suspension performance	~		
						⊢⊢	Steering performance	~		
						\square	Shock absorbers	~		
						A	r Conditioning / Heater			
						ᅪᄂ	Operation		~	
Interior Comments						E	lectrical / Accessories			
Seats	seats are r	ipped,wear and t	ear,minor stains ,			IH	Head lights	~		
	woarandi	tear,minor stains					Tail lights	~		
Carpets	wear and		1				Indicators	~		
Panels	Average						Dashboard warning lights	~		
						1 -	Wipers (front & rear)	~		
Dashboa	ard Average						Window winder FL	~		
	1					╎┝	Window winder FR	~		
General Comments							Window winder RL		~	
Has a slight	shudder ,					⊢⊢	Window winder RR	~		
							Rear view mirrors		~	
							Radio (basic test only)	~		
							CD (basic test only)	~		
						IL	Number of keys	1		1
Road Conditions During Test Drive: Wet						- ⊢	Central locking	~		
			Wet			\square	Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain				Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera			~
	•	•								•
Inspected by: Donovan Matara Date: 14 Sep 2017										

I have read and understood this condition guide.

Name:

Signature: