

Report ID: 16,665,647 Version: 3 Created: 29 Sep 2017

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2,013	Registration:	GWW368	Reg Expiry:	30 Dec 2017	Engine			
WoF Expiry:	10 Aug 2018	Odometer:	103,230 Kms	Good No:	16665647	Oil level	~		
VIN:	KMHSH81XSCU90600	Next Service:	110000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Dauta have used	harry alternational and	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	v		
Key:	sc	-0	SC	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	eration 🖌		
R = rust PT = paint defe				\int	JHIH	Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent					세비	CV joints	~		•
* = decals	SD 919			The		Wheel bearings	v		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	mav not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	of tyre) (
					Left front 3.0 mm				
					Right front	5.0		 	
						Left rear	5 5.0		mm
Conditions During Rody Inspection:						Right rear	3.0 mm 3.0 mm		
Conditions During Body Inspection: Dry						Spare	5.0		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
	•	·				Suspension performance	~		
						Steering performance	~		
Shock absorbe							~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories			
Seats drivers seat ripped, wear and tear, minor stains.						Head lights	~		
Jeats						Tail lights	~		
Carpets	wear and t	ear,minor stains	1			Indicators	~		
Panels	the rear sid	de covers need a	ttention,scratched ,			Dashboard warning lights	~		
Pariers						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Boad Conditions During Test Driver Date						Central locking	2		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Tir	ning Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									_
Inspected by: Donovan Matara Date: 01 Sep 2017									

I have read and understood this condition guide.

Name:

Signature: