

Report ID: 16,666,393

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 09 Oct 2017

Pass

~

~

/

1

Tyres (lowest observed tread depth of tyres)

N/A

1

mm

mm

mm

 mm

~

1

4

2

3


Yes

Fail

Make: Model: **Body Style:** Sedan Volkswagen Jetta Year: Registration: **Reg Expiry:** 2,006 **DNJ728** 25 Aug 2017 **WoF Expiry: Odometer: Good No:** 17 Oct 2017 104,257 Kms 16666393 VIN: **Next Service: Service History:** WVWZZZ1KZ6M81080 108000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Right hand tail light broken

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Good	
Dashboard	Good	

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Donovan Matara

Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights V Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR 1 Rear view mirrors Radio (basic test only) ~ CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) Reversing camera

09 Oct 2017

Date:

I have read and understood this condition guide.	Name:	Signature:

Kms: