

Report ID: 16,667,353 Version: 1 Created: 31 Aug 2017

Make:	Hyundai	Model:	140	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,013	Registration:	GYC125	Reg Expiry:	30 Sep 2017	Engine			<u> </u>
WoF Expiry:	2,013 07 Jun 2018	Odometer:	96,526 Kms	Good No:	16667353	Oil level	~		
VIN:	KMHLB81UMDU06351		110000	Service Histor		Smoke & fumes	~		
			110000		103	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
		_				Performance	ン ン		
Key:		-0	LIS			Radiator / Hoses (visual)			
S = scratch	Se	20		105	*	Transmission	~		
D = dent	s alt				EID S				T
R = rust				10		Operation	~		
PT = paint def	ect 📊			$ \cup$		Noise	~		<u> </u>
C = crack P = pin dent	Ht			-		Clutch			~
* = decals	dig				ELA S	CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs						Brakes			
	S			S		Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Right side mirror cover crack						Tyres (lowest observed tread depth of tyres)			
						Left front	5	5	mm
						Right front	e	5	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		1
Dashboa	rd Good					Window winder FL	~		<u> </u>
	1					Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		<u> </u>
						Window winder RR	~		+
						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		
						Number of keys	2		L
Bood Car						Central locking	2		
Road Conditions During Test Drive: Wet Central locking Remote locking Remote locking							~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			<i>v</i> <i>v</i>
Inspected by: Jason Law Date: 31 Aug 2017									

I have read and understood this condition guide.

Name: