

Report ID: 16,677,913 Version: 1 Created: 08 Sep 2017

Make:	Hyundai	Model:	140	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,013	Registration:	GYU976	Reg Expiry:	24 Sep 2017	Engine			I
WoF Expiry:	27 Jun 2018	Odometer:	110,877 Kms	Good No:	16677913	Oil level	~		
VIN:	KMHLB81UMDU0654	Next Service:	120.000	Service Histor		Smoke & fumes	· ·		
			.20,000			Performance	~		
	port is not a warranty		с I II			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and the	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	ls		s	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			T	Transmission	v		
D = dent	sc w			1n-	EL SC W	Operation	~		
R = rust				1 M	JHIA	Noise	~		
PT = paint def C = crack				+	SC	Clutch	•		~
P = pin dent	Ho				JUII —	CV joints	~		V
* = decals	sc PIC			AL-		Wheel bearings			
SC = stone chips						Wheel bearings			
W = significant scuffs W									
			Lefects & blemishes			Performance	~		
Body Insp	pection Comments	Note: som	ie defects & biemisnes	may not be disp	layed in the diagram	Hand Brake	~	<i>C</i> :	,
					Tyres (lowest observed tread depth of tyres)				
						Left front	4.	3	mm
						Right front	4.	5	mm
						Left rear	6.	6	mm
Conditions During Body Inspection: Dry						Right rear	6.9 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	rriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
		Shock absorbers	~						
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			Jy			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ian Dunn Date: 08 Sep 2017									

I have read and understood this condition guide.

Name:

Signature: