

Report ID: 16,680,117 Version: 1 Created: 06 Sep 2017

Make:	Toyota	Model:	Allex	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,004	Registration:	FDP299	Reg Expiry:	06 Jul 2017	Engine			
WoF Expiry:	06 Dec 2017	Odometer:	162,856 Kms	Good No:	16680117	Oil level	~		
VIN:	7A8H63Y0709294504	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SD	-0	SPSC SP*		S D	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust S D SC S D						Transmission			
						Operation	~		
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIC				게	CV joints	~		-
* = decals	ssc 916			-Jul	HIP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D S P SC S P SC S P SC S D						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread depth of tyres)			
Moisture inside RHR tail light ,hub caps missing off LH side x2,									mm
						Right front			 mm
						Left rear	3		mm
						Right rear	0		mm
Conditions During Body Inspection: Wet						Spare	•		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
Stee						Steering performance	~		
						Shock absorbers	~		
							V		
						Air Conditioning / Heater			
Interior Comments						Operation			
cigarette holes drivers seat wear and tear stains						Electrical / Accessories			
Seats	5					Head lights	~		
Carpets	wear and t	ear,minor stains	,			Tail lights	~		
	Average					Indicators	~		
Panels	/ incluge					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		
<u>General Comments</u> Flat battery needed jump start,does shudder a little when idling and coming to a stop ,						Window winder RL	~		
	needed jump start, doe	s shudder a neae	when raining and com	ing to a stop ,		Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet							~		
Enging Ti	ning Machanism	 ···	2 1 • .			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 06 Sep 2017									

I have read and understood this condition guide.

Name: