

## **Basic Vehicle Condition Guide**

Report ID: 16,838,670


Version: 2

Created: 14 Mar 2018

Make: Model: Hino Dutro **Body Style:** Van Year: 2,008 Registration: Reg Expiry: HBL66 04 Apr 2018 WoF Expiry: **Odometer: Good No:** 202,399 Kms 16838670 VIN: **Next Service: Service History:** 7AT0842EX13002736 228,000kms

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

OK.

Interior Comments				
Seats	Drivers seat ripped, burns in left seat.			
Carpets	rips.			
Panels	Average			
Dashboard	Average			

## **General Comments**

Drives ok on road.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 08 Sep 2017

		1	
	Pass	Fail	N/A
Engine		ı	
Oil level	~		
Smoke & fumes	\( \times \)		
Performance	~		
Noise	~		
Cooling System	1	1	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	\( \triangle \)		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4	.0	mm
Right front	5	.0	mm
Left rear	6	.0	mm
Right rear	7.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1		
Operation	~		
Electrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\( \times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	<u> </u>		V
Window winder RR			V
Rear view mirrors	V		Ť
Radio (basic test only)	~		
CD (basic test only)	<del>-</del>		<b>1</b>
Number of keys	1		
Central locking	<u>'</u>		
Remote locking			.,
Sat. Nav. (basic test only)			1.1
-			.,
Reversing camera			

I have read and understood this condition guide.

Name:			