

Report ID: 16,855,188 Version: 2 Created: 16 Oct 2017

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2,008	Registration:		Reg Expiry:	22 Oct 2017	Engine			L
WoF Expiry:	24 May 2018	Odometer:	62,700 Kms	Good No:	16855188	Oil level	~		
VIN:	7AT0H60FX12008071	Next Service:	75000	Service Histor	' y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	SD.	-01-	SD	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S SC D PT						Operation	~		
PT = paint defe	ect NP	FI		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints			~
* = decals D SC 000 SD						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D S D S D						Performance 🖌			
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
LR lens broken, Many dents on panels. Tailgate window broken						Left front	. 9.	0	mm
						Right front	9		mm
						Left rear	7.		mm
Conditions During Body Inspection: Wet						Right rear	7.	-	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation		~	
Interior Comments						Electrical / Accessories		·	<u> </u>
Seats	Average					Head lights	~		
	A					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL			~
						Window winder FR			~
General Comments					Window winder RL			~	
Drives OK						Window winder RR			~
						Rear view mirrors	~		-
						Radio (basic test only)	~		
						CD (basic test only)	•		~
						Number of keys	1		
Boad Conditions During Test Drives						Central locking	· ·		
Road Conditions During Test Drive: Wet						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			<i>v</i> <i>v</i>
	-1	ľ							
Inspected by: Stuart Melbourne Date: 22 Sep 2017									
I have read and understood this condition guide. Name:									