

## **Basic Vehicle Condition Guide**

Report ID: 16,856,517

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

26 Mar 2019 Created:

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

4

3

3

1

/

/

/

1

1

1

Yes


Make: Subaru Model: Forester **Body Style:** SUV

Year: 2009 Registration: FDM60 **Reg Expiry:** WoF Expiry: **Odometer:** 26 Mar 2020 239,548 Kms **Good No:** 

16856517 VIN: JF2SH9KL5AG036243 **Next Service: Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Conditions During Body Inspection:

Rear tow eye cover missing

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Good	

Wet

## **General Comments**

Inspected by:

Left wing mirror not working Remote key not working Gear release button missing Suspension knocking noise

**Road Conditions During Test Drive:** Wet

**Engine Timing Mechanism:** Cambelt **Evidence of Cam Belt Replacement:** No

**Bobby Zhong** 

I have read and understood this condition guide.

Kms:	Sat. Nav. (basic test only)  Reversing camera	V V	
Date: 26 Mar 2019			
Name:	Signature:		