

Report ID: 16,856,627 Version: 2 10 Oct 2017 Created:

| Make: | Hyundai | Model: | Santa FE | Body Style: | SUV | | Pass | Fail | N/A |
|---|--|-------------------------------------|---|--------------------------------------|---------------------------|------------------------------|-------|--------|------------|
| Year: | Hyundai | Registration: | Santa FE HEM948 | Reg Expiry: | | Engine | 1 435 | i uli | |
| WoF Expiry: | 2,013 | Odometer: | | Reg Expiry: Good No: | 11 Dec 2017 | Oil level | | | |
| | 23 Feb 2018 | | 130,007 Kms | Service Histor | 16856627 | | ~ | | <u> </u> |
| VIN: | KMHST81XSEU250448 | Next Service: | 138,000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| Note: This re | port is not a warranty | | | | | Performance | ~ | | |
| This report is | a guide only. Conside | | | | | Noise | ~ | | |
| a full mechar | sting undertaken. The v lical inspection prior to | vehicle has beer purchase and th | n driven up to 50km/h his can be arranged fo | from cold. The or an additional o | Vendor recommends charge. | Cooling System | | | |
| | · · | • | 5 | | 5 | Coolant condition | ~ | | |
| Key: | | \sim | | | | Performance | ~ | | |
| S = scratch | | $\overline{(0)}$ | | 5(O)- | | Radiator / Hoses (visual) | ~ | | |
| D = dent | | | | | AD | Transmission | | | |
| R = rust | s sc | | | 10 | | Operation | ~ | | |
| PT = paint def | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HIP | | | | 7414 | CV joints | ~ | | |
| * = decals | sc 91 | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | Performance | ~ | | |
| | | Note: son | ne defects & blemishes | may not be disc | blaved in the diagram | Hand Brake | ~ | | |
| Body inspection Comments | | | | | | Tyres (lowest observed tread | | oftyre | <u> </u> |
| Scratch ma | rk on passenger windov | V | | | | Left front | · · | | |
| | | | | | | Right front | 1 | | |
| | | | | | | Left rear | 2 | | mm |
| | | | | | | | 1 | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3 | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | inage & onder bor | mermspectic | <u>on comments</u> | | | Suspension | | | . <u> </u> |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | _ | | _ |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | <u> </u> |
| | I | | | | | Window winder FR | ~ | | <u> </u> |
| General (| <u>Comments</u> | | | | | Window winder RL | V | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | . ,. | | | L |
| | 1 | | | | | Number of keys | 2 | | <u> </u> |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Remote locking | ~ | | . |
| | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Lvidence | | Ciriciit. N | lot Applicable | 11115. | | Reversing camera | ~ | | |
| Inspecte | d by: Donovan Matar | Date: 10 Oct 2017 | | | | | | | |
| | | ~ | | | | | •• | | |
| I have read | and understood th | is condition g | juide. Name: | | | Signature: | | | |