

Basic Vehicle Condition Guide

Report ID: 16,862,482


Version:

Created: 28 Sep 2017

Make: Model: Bluebird **Body Style:** Sedan Nissan Year: 1,992 Registration: Reg Expiry: 10 Oct 2017 XG2193 WoF Expiry: **Odometer: Good No:** 21 Mar 2018 242,129 Kms 16862482 VIN: **Next Service: Service History:** 7A8DH1E0798095527 252,100 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Coolant dirty.

Drivebelt worn.

Multiple engine oil leaks.

RF inner and outer CV boots split.

Front brakes low.

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Noise in suspension. Requires wheel alignment.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Scott Willoughby Date: 28 Sep 2017

Name:

Pass	Fail	N/A
~		
~		
~		
~		
		1
	~	
~		
~		
1		1
~		
~		
		~
~		
~		
	~	
~		
d depth	of tyre	 es)
<u> </u>	 1	mm
-		mm
-		mm
		mm
	~	
	~	
~		
		1
	~	
~		
~		
~		
~		
	~	
~		
~		
~		
~		
~		
· ·	~	
	-	1
1		
~		
		~
		~
		1
		V

Signature: