

Report ID: 16,863,379 Version: 1 16 Oct 2017 Created:

Make:	Suzuki	Model:	Kizashi	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,013	<b>Registration:</b>		Reg Expiry:	18 Jan 2018	Engine	1	<u> </u>	
WoF Expiry:	23 Mar 2018	Odometer:	72,176 Kms	Good No:	16863379	Oil level	~		
VIN:	JSAFRE91S00123023	Next Service:	0	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	s sc	-0	S P SC	-161-	S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIS	S D SC	Operation	~		
R = rust PT = paint def				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					PT SC	Clutch	-		~
P = pin dent	HIG				세비	CV joints	~		
* = decals	SDSC 91			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs SC	$- \varnothing$	P SC S P SC		S P SC	Performance	~		
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inst	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	of tyre	es)
					Left front 7 mm				
						Right front			mm
						Left rear		, 5	mm
Condition	ns During Pody Inc	naction.				Right rear		-	 mm
Conditions During Body Inspection: Dry						Right rear 6 mm   Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ard Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Pood Conditions During Test Driver						Central locking			
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•	•							-
Inspected by: Donovan Matara Date: 16 Oct 2017									

I have read and understood this condition guide.

Name: .....